Ship Fact Sheet

\rightarrow

KOAU (1917)

Base data at August 1917. Compiled February 2009 * indicates entries changed during P&O Group service.

P&

<i>Type P&O Group service P&O Group status Former name(s)</i>	General cargo ship 1917-1952 Owned by subsidiary company
Registered owners, managers and operators	Richardson & Company
Builders Yard Country Yard number	Brown & Sons Te Kopuru New Zealand
Registry Official number Signal letters Call sign	121596
Classification society	Lloyd's Register
Gross tonnage Net tonnage Deadweight	144 grt 77 nrt
Length Breadth Depth Draught Construction (if not steel)	26.73m (87.7ft) 6.70m (22.0ft) 2.89m (9.5ft)
Engines* Engine builders Works Country	Twin standard O E Co petrol engines
Power* Propulsion Speed	85 bhp each
Passenger capacity Cargo capacity Crew	
Employment	

R&C 1917/08

Career

1917:	Completed.
17.07.1918:	Stranded in the Wairoa River, sustaining slight damage.
02.11.1926:	Stranded in Wangaehu Bay, although she did not sustain any damage.
09.1929/	Re-engined at Auckland with twin Fairbanks-Morse 3-cylinder diesels
11.1929:	each developing 75 bhp.
02.01.1929:	Collided with the launch Venture at Napier.
22.11.1933:	Collided with the launch <i>Doris</i> at Napier.
26.02.1935:	Damaged her port engine while on a voyage from Napier to Tolaga Bay.
28.11.1940:	Damaged her propellers.
27.04.1941:	Involved in a collision with the lighter <i>Moa</i> at Napier.
11.06.1942:	Broke her tailshaft off in Hawke's Bay. She was towed to Gisborne, and then to Napier for repairs.
08.1942/	Had her wheelhouse enclosed in an extensive refit.
11.1942:	
09.1950:	Had a deckhouse added to the after end of the foredeck.
04.1952:	Sold to the Southern Cross Shipping Company, Picton (Holm & Co, managers).
09.1952:	Renamed <i>Picton</i> .
1955:	Re-engined with twin 6-cylinder Gardner diesels each developing 114 bhp. Re-measured. Now 150 grt, 75 nrt.
02.01.1959:	Stranded on a mudbank while leaving Waitapu for Lyttleton. She was refloated undamaged three days later.
12.01.1959:	Struck by the trawler <i>Taiaroa</i> while berthed at Wellington.
12.05.1961:	Twice grounded on the spit while entering the Waimakariri River. She was refloated six days later and berthed at Kaiapoi.
31.05.1961:	Towed to Lyttelton for repairs.
1963:	Laid up at Wellington.
06.1964:	Sold to the Picton Fishing Co for line fishing.
10.1964:	Fitted with a freezer unit.
1965:	Duties included crayfishing at the Chatham Islands.
10.07.1966:	Her hull was pierced and fractured when a cradle bearer collapsed on the Lyttelton patent slip.
20.07.1978:	Wrecked on Raoul Island while under charter to the Ministry of Transport. Her crew was rescued by HMNZS <i>Tui</i> .

- ends -